

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin

LD0001G	Total LMA Miles	12.45										
Levee District No. 0001 (Glenn County)	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		M					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.97		0.97	7.79	1.05		1.05	8.43	0.08		0.08	0.64
Trim / Thin Trees	0.11		0.11	0.88	0.11		0.11	0.88				0.00
Encroachments	0.37		0.37	2.97	0.34		0.34	2.73	-0.03		-0.03	-0.24
Animal Control	0.74		0.74	5.94	0.42		0.42	3.37	-0.32		-0.32	-2.57
<i>LMA Totals:</i>	2.19	0.00	2.19	17.59	1.92	0.00	1.92	15.42	-0.27	0.00	-0.27	-2.17
LD0001S	Total LMA Miles	16.65										
Levee District No. 0001 (Sutter County)	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
No Items												0.00
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
LD0002	Total LMA Miles	4.89										
Levee District No. 0002 (Glenn County)	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control					0.13		0.13	2.66	0.13		0.13	2.66
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.13	0.00	0.13	2.66	0.13	0.00	0.13	2.66
LD0003	Total LMA Miles	12.24										
Levee District No. 0003 (Glenn County)	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees					0.01		0.01	0.08	0.01		0.01	0.08
Encroachments	0.01		0.01	0.08	0.02		0.02	0.16	0.01		0.01	0.08
Animal Control	0.66		0.66	5.39	0.16		0.16	1.31	-0.50		-0.50	-4.09
Slope Stability	0.03		0.03	0.25	0.02		0.02	0.16	-0.01		-0.01	-0.08
Crown Surface / Depressions / Rutting	0.04		0.04	0.33					-0.04		-0.04	-0.33
<i>LMA Totals:</i>	0.74	0.00	0.74	6.05	0.21	0.00	0.21	1.72	-0.53	0.00	-0.53	-4.33
LD0009	Total LMA Miles	6.24										
Levee District No. 0009 (Sutter County)	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.01		0.01	0.16	6.56		6.56	105.13	6.55		6.55	104.97
Erosion / Bank Caving	0.07		0.07	1.12	0.07		0.07	1.12				0.00
<i>LMA Totals:</i>	0.08	0.00	0.08	1.28	6.63	0.00	6.63	106.25	6.55	0.00	6.55	104.97

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

MA0001	Total LMA Miles	17.12										
Sutter Maintenance Yard Maintenance Area 0001	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01		0.01	0.06	0.02		0.02	0.12	0.01		0.01	0.06
Trim / Thin Trees	0.05		0.05	0.29	0.03		0.03	0.18	-0.02		-0.02	-0.12
Encroachments	0.06		0.06	0.35	0.02		0.02	0.12	-0.04		-0.04	-0.23
Animal Control	1.90		1.90	11.11	1.61		1.61	9.40	-0.29		-0.29	-1.71
Erosion / Bank Caving	0.01		0.01	0.06	0.01		0.01	0.06				0.00
<i>LMA Totals:</i>	2.03	0.00	2.03	11.87	1.69	0.00	1.69	9.87	-0.34	0.00	-0.34	-2.00
MA0003	Total LMA Miles	5.19										
Sutter Maintenance Yard Maintenance Area 0003	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.12		0.12	2.31					-0.12		-0.12	-2.31
Animal Control	0.01		0.01	0.19	0.01		0.01	0.19				0.00
<i>LMA Totals:</i>	0.13	0.00	0.13	2.50	0.01	0.00	0.01	0.19	-0.12	0.00	-0.12	-2.31
MA0004	Total LMA Miles	3.40										
Sacramento Maintenance Yard Maintenance Area 0004	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees					0.16		0.16	4.71	0.16		0.16	4.71
Animal Control	0.01		0.01	0.29					-0.01		-0.01	-0.29
<i>LMA Totals:</i>	0.01	0.00	0.01	0.29	0.16	0.00	0.16	4.71	0.15	0.00	0.15	4.41
MA0005	Total LMA Miles	33.32										
Sutter Maintenance Yard Maintenance Area 0005	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.10		0.10	0.30	0.02		0.02	0.06	-0.08		-0.08	-0.24
Trim / Thin Trees	0.20		0.20	0.60					-0.20		-0.20	-0.60
Encroachments	0.05		0.05	0.15	0.04		0.04	0.12	-0.01		-0.01	-0.03
Animal Control	0.37		0.37	1.11	0.16		0.16	0.48	-0.21		-0.21	-0.63
Slope Stability	0.02		0.02	0.06	0.03		0.03	0.09	0.01		0.01	0.03
Repair Gates	0.01		0.01	0.03	0.01		0.01	0.03				0.00
USACE Erosion Survey		0.01	0.04	0.12		0.01	0.04	0.12				0.00
<i>LMA Totals:</i>	0.75	0.01	0.79	2.37*	0.26	0.01	0.30	0.90*	-0.49	0.00	-0.49	-1.46

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

MA0007	Total LMA Miles	12.07										
Sutter Maintenance Yard Maintenance Area 0007	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.02		0.02	0.17	0.01		0.01	0.08	-0.01		-0.01	-0.08
Animal Control	0.03		0.03	0.25					-0.03		-0.03	-0.25
Erosion / Bank Caving	0.07		0.07	0.58	0.02		0.02	0.17	-0.05		-0.05	-0.41
<i>LMA Totals:</i>	0.12	0.00	0.12	0.99	0.03	0.00	0.03	0.25	-0.09	0.00	-0.09	-0.74
MA0009	Total LMA Miles	19.61										
Sacramento Maintenance Yard Maintenance Area 0009	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.15		0.15	0.77	0.14		0.14	0.71	-0.01		-0.01	-0.05
Trim / Thin Trees	0.17		0.17	0.87	0.04		0.04	0.20	-0.13		-0.13	-0.66
Encroachments	0.05		0.05	0.26	1.81		1.81	9.23	1.76		1.76	8.98
Animal Control	0.01		0.01	0.05	0.06		0.06	0.31	0.05		0.05	0.26
Erosion / Bank Caving					0.01		0.01	0.05	0.01		0.01	0.05
USACE Erosion Survey		0.04	0.16	0.82		0.04	0.16	0.82				0.00
<i>LMA Totals:</i>	0.38	0.04	0.54	2.76*	2.06	0.04	2.22	11.32	1.68	0.00	1.68	8.57
MA0012	Total LMA Miles	11.31										
Sutter Maintenance Yard Maintenance Area 0012	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.02		0.02	0.18					-0.02		-0.02	-0.18
<i>LMA Totals:</i>	0.02	0.00	0.02	0.18	0.00	0.00	0.00	0.00	-0.02	0.00	-0.02	-0.18
MA0013	Total LMA Miles	41.97										
Sutter Maintenance Yard Maintenance Area 0013	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.07		0.07	0.17					-0.07		-0.07	-0.17
Trim / Thin Trees	0.26		0.26	0.62					-0.26		-0.26	-0.62
Encroachments	0.55		0.55	1.31	0.18		0.18	0.43	-0.37		-0.37	-0.88
Animal Control	0.01		0.01	0.02					-0.01		-0.01	-0.02
Erosion / Bank Caving	0.17	0.36	1.61	3.83	0.46	0.36	1.90	4.53	0.29		0.29	0.69
USACE Erosion Survey	0.37		0.37	0.88	0.36		0.36	0.86	-0.01		-0.01	-0.02
<i>LMA Totals:</i>	1.43	0.36	2.87	6.83*	1.00	0.36	2.44	5.81*	-0.43	0.00	-0.43	-1.02

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

MA0016	Total LMA Miles	4.09										
Sutter Maintenance Yard Maintenance Area 0016	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.33		0.33	8.05					-0.33		-0.33	-8.05
Encroachments	0.02		0.02	0.49					-0.02		-0.02	-0.49
Animal Control	0.25		0.25	6.10					-0.25		-0.25	-6.10
<i>LMA Totals:</i>	0.60	0.00	0.60	14.63	0.00	0.00	0.00	0.00	-0.60	0.00	-0.60	-14.63
NA0001	Total LMA Miles	33.24										
American River Flood Control District	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.08		0.08	0.24	0.08		0.08	0.24
Encroachments	0.02		0.02	0.06	0.28		0.28	0.84	0.26		0.26	0.79
Animal Control					0.32		0.32	0.96	0.32		0.32	0.96
Slope Stability					0.02		0.02	0.06	0.02		0.02	0.06
<i>LMA Totals:</i>	0.02	0.00	0.02	0.06	0.70	0.00	0.70	2.11	0.68	0.00	0.68	2.05
NA0002	Total LMA Miles	19.32										
Brannan Andrus Levee Maintenance District	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.78	0.57	3.06	15.85					-0.78	-0.57	-3.06	-15.85
Trim / Thin Trees	0.61	0.44	2.37	12.28	0.49		0.49	2.54	-0.12	-0.44	-1.88	-9.74
Encroachments	0.02		0.02	0.10					-0.02		-0.02	-0.10
USACE Erosion Survey		0.01	0.04	0.21					-0.01	-0.04	-0.04	-0.21
<i>LMA Totals:</i>	1.41	1.02	5.49	28.45	0.49	0.00	0.49	2.54	-0.92	-1.02	-5.00	-25.91
NA0003	Total LMA Miles	24.71										
Butte County Public Works	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01		0.01	0.04					-0.01		-0.01	-0.04
Encroachments	0.41		0.41	1.66	0.09		0.09	0.36	-0.32		-0.32	-1.29
Animal Control	0.05		0.05	0.20	0.09		0.09	0.36	0.04		0.04	0.16
Slope Stability	0.01		0.01	0.04	0.01		0.01	0.04				0.00
<i>LMA Totals:</i>	0.48	0.00	0.48	1.94	0.19	0.00	0.19	0.77	-0.29	0.00	-0.29	-1.17
NA0004	Total LMA Miles	11.38										
Marysville Levee Commission	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					0.48		0.48	4.22	0.48		0.48	4.22
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.48	0.00	0.48	4.22	0.48	0.00	0.48	4.22

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

NA0005	Total LMA Miles	3.63										
City of Sacramento	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01		0.01	0.28	0.01		0.01	0.28				0.00
Encroachments					0.01		0.01	0.28	0.01		0.01	0.28
<i>LMA Totals:</i>	0.01	0.00	0.01	0.28	0.02	0.00	0.02	0.55	0.01	0.00	0.01	0.27
NA0006	Total LMA Miles	1.50										
Sutter Maintenance Yard Eastern Honcut Creek	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.96		2.96	197.33	2.87		2.87	191.33	-0.09		-0.09	-6.00
Crown Surface / Depressions / Rutting	0.73		0.73	48.67	0.67	1.39	6.23	415.33	-0.06	1.39	5.50	366.67
<i>LMA Totals:</i>	3.69	0.00	3.69	246.00	3.54	1.39	9.10	606.67	-0.15	1.39	5.41	360.67
NA0008	Total LMA Miles	12.57										
Knights Landing Ridge Drainage District	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.08		0.08	0.64	0.44		0.44	3.50	0.36		0.36	2.87
Trim / Thin Trees	0.01		0.01	0.08	0.01		0.01	0.08				0.00
Encroachments	0.01		0.01	0.08	0.24		0.24	1.91	0.23		0.23	1.83
Animal Control	0.05		0.05	0.40	0.06		0.06	0.48	0.01		0.01	0.08
USACE Erosion Survey	2.27		2.27	18.02	2.20		2.20	17.50	-0.07		-0.07	-0.51
<i>LMA Totals:</i>	2.42	0.00	2.42	19.21	2.95	0.00	2.95	23.47	0.53	0.00	0.53	4.26
NA0012	Total LMA Miles	0.59										
Solano County Public Works Mellin Levee	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		M					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.59		0.59	100.00	0.10		0.10	16.95	-0.49		-0.49	-83.05
Encroachments	0.02		0.02	3.39					-0.02		-0.02	-3.39
Slope Stability	0.01		0.01	1.70					-0.01		-0.01	-1.70
Crown Surface / Depressions / Rutting	0.31		0.31	52.54					-0.31		-0.31	-52.54
<i>LMA Totals:</i>	0.93	0.00	0.93	157.63	0.10	0.00	0.10	16.95	-0.83	0.00	-0.83	-140.68
NA0014	Total LMA Miles	0.78										
Murphy Slough at M&T Ranch	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.30		1.30	166.67	1.56		1.56	200.00	0.26		0.26	33.33
Trim / Thin Trees	0.62		0.62	79.49	0.75		0.75	96.15	0.13		0.13	16.67
<i>LMA Totals:</i>	1.92	0.00	1.92	246.15	2.31	0.00	2.31	296.15	0.39	0.00	0.39	50.00

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

NA0016	Total LMA Miles		50.21									
Sacramento River West Side Levee District	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.05		0.05	0.10	0.05		0.05	0.10				0.00
Trim / Thin Trees	0.04		0.04	0.08	0.03		0.03	0.06	-0.01			-0.01 -0.02
Encroachments	0.05		0.05	0.10	0.09		0.09	0.18	0.04			0.04 0.08
Animal Control	0.15		0.15	0.30	0.17		0.17	0.34	0.02			0.02 0.04
USACE Erosion Survey		0.04	0.16	0.32		0.04	0.16	0.32				0.00
<i>LMA Totals:</i>	0.29	0.04	0.45	0.90*	0.34	0.04	0.50	1.00*	0.05	0.00	0.05	0.10
NA0018	Total LMA Miles		0.30									
California Department of Fish and Game Shea Levee	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
No Items												0.00
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
NA0019	Total LMA Miles		13.64									
Tehama County Flood Control and Water Conservation District	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		M					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.66		0.66	4.84	0.72		0.72	5.28	0.06		0.06	0.44
Trim / Thin Trees	0.14		0.14	1.03	0.14		0.14	1.03				0.00
Encroachments	0.65		0.65	4.77	0.52		0.52	3.81	-0.13		-0.13	-0.95
Animal Control	0.01		0.01	0.07	0.01		0.01	0.07				0.00
Slope Stability	0.25		0.25	1.83	0.28		0.28	2.05	0.03		0.03	0.22
Erosion / Bank Caving	0.01		0.01	0.07	0.02		0.02	0.15	0.01		0.01	0.07
USACE Erosion Survey	0.07		0.07	0.51	0.01		0.01	0.07	-0.06		-0.06	-0.44
<i>LMA Totals:</i>	1.79	0.00	1.79	13.12	1.70	0.00	1.70	12.46	-0.09	0.00	-0.09	-0.66
NA0020	Total LMA Miles		4.76									
Sutter Maintenance Yard East-West Interceptor	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.17		3.17	66.60	3.17		3.17	66.60				0.00
Trim / Thin Trees	0.24		0.24	5.04					-0.24		-0.24	-5.04
Encroachments	0.16		0.16	3.36	0.12		0.12	2.52	-0.04		-0.04	-0.84
Erosion / Bank Caving	0.43		0.43	9.03	0.43		0.43	9.03				0.00
<i>LMA Totals:</i>	4.00	0.00	4.00	84.03	3.72	0.00	3.72	78.15	-0.28	0.00	-0.28	-5.88

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

NA0021	Total LMA Miles	0.29											
Yolo County Public Works	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		M		Overall LMA Rating		U						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation					0.84		0.84	289.66	0.84		0.84	289.66	
Trim / Thin Trees	0.05		0.05	17.24	0.09		0.09	31.03	0.04		0.04	13.79	
Encroachments					0.01		0.01	3.45	0.01		0.01	3.45	
<i>LMA Totals:</i>	0.05	0.00	0.05	17.24	0.94	0.00	0.94	324.14	0.89	0.00	0.89	306.90	
NA0022	Total LMA Miles	5.97											
Yolo County Service Area 6	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		M		Overall LMA Rating		A						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	0.56		0.56	9.38	0.44		0.44	7.37	-0.12		-0.12	-2.01	
Trim / Thin Trees	0.01		0.01	0.17	0.02		0.02	0.34	0.01		0.01	0.17	
Encroachments	0.05		0.05	0.84	0.06		0.06	1.01	0.01		0.01	0.17	
Animal Control					0.03		0.03	0.50	0.03		0.03	0.50	
<i>LMA Totals:</i>	0.62	0.00	0.62	10.39	0.55	0.00	0.55	9.21	-0.07	0.00	-0.07	-1.17	
RD0003	Total LMA Miles	28.65											
Reclamation District No. 0003 Grand Island	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		M *						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	35.38		35.38	123.71		0.01	0.04	0.14	-35.38	0.01	-35.34	-123.57	
Trim / Thin Trees	3.94	0.64	6.50	22.73	0.55	0.11	0.99	3.46	-3.39	-0.53	-5.51	-19.27	
Encroachments	0.17		0.17	0.59	0.01		0.01	0.04	-0.16		-0.16	-0.56	
Slope Stability	0.06		0.06	0.21					-0.06		-0.06	-0.21	
Repair Gates	0.01		0.01	0.04					-0.01		-0.01	-0.04	
USACE Erosion Survey	0.29		0.29	1.01	0.29		0.29	1.01				0.00	
<i>LMA Totals:</i>	39.85	0.64	42.41	148.29	0.85	0.12	1.33	4.64*	-39.00	-0.52	-41.08	-143.64	
RD0010	Total LMA Miles	21.93											
Reclamation District No. 0010 Honcut	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		A						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	24.02		24.02	109.68	0.44		0.44	2.01	-23.58		-23.58	-107.67	
Trim / Thin Trees	0.05		0.05	0.23	0.04		0.04	0.18	-0.01		-0.01	-0.05	
Encroachments	0.02	0.12	0.50	2.28	0.03		0.03	0.14	0.01	-0.12	-0.47	-2.15	
Animal Control	0.03		0.03	0.14	0.08		0.08	0.37	0.05		0.05	0.23	
Culverts: Inlets / Outlets	0.01		0.01	0.05					-0.01		-0.01	-0.05	
<i>LMA Totals:</i>	24.13	0.12	24.61	112.37	0.59	0.00	0.59	2.69	-23.54	-0.12	-24.02	-109.68	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0070	Total LMA Miles	23.57											
Reclamation District No. 0070 Meridian	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.07		0.07	0.30						-0.07		-0.07	-0.30
USACE Erosion Survey	0.29		0.29	1.23	0.29		0.29	1.23					0.00
<i>LMA Totals:</i>	0.36	0.00	0.36	1.53	0.29	0.00	0.29	1.23	-0.07	0.00	-0.07	-0.30	
RD0108	Total LMA Miles	20.59											
Reclamation District No. 0108 River Farms	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.02		0.02	0.10	0.02		0.02	0.10					0.00
Trim / Thin Trees					0.89		0.89	4.32	0.89		0.89		4.32
Animal Control	0.02		0.02	0.10	0.06		0.06	0.29	0.04		0.04		0.19
Cracking					0.03		0.03	0.15	0.03		0.03		0.15
<i>LMA Totals:</i>	0.04	0.00	0.04	0.19	1.00	0.00	1.00	4.86	0.96	0.00	0.96		4.66
RD0150	Total LMA Miles	18.07											
Reclamation District No. 0150 Merritt Island	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		M *		Overall LMA Rating		M						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.22		0.22	1.22	0.19		0.19	1.05	-0.03		-0.03		-0.17
Trim / Thin Trees	0.53		0.53	2.93	0.37		0.37	2.05	-0.16		-0.16		-0.89
Encroachments	0.13		0.13	0.72	0.30		0.30	1.66	0.17		0.17		0.94
Animal Control	0.20		0.20	1.11	0.05		0.05	0.28	-0.15		-0.15		-0.83
Slope Stability	0.03		0.03	0.17	0.08		0.08	0.44	0.05		0.05		0.28
Erosion / Bank Caving	0.08		0.08	0.44	0.14		0.14	0.78	0.06		0.06		0.33
Crown Surface / Depressions / Rutting	0.01		0.01	0.06	0.43		0.43	2.38	0.42		0.42		2.33
Metal Pipes					0.01		0.01	0.06	0.01		0.01		0.06
USACE Erosion Survey	0.03	0.09	0.39	2.16	0.03	0.09	0.39	2.16					0.00
<i>LMA Totals:</i>	1.23	0.09	1.59	8.80*	1.60	0.09	1.96	10.85	0.37	0.00	0.37		2.05
RD0307	Total LMA Miles	6.65											
Reclamation District No. 0307 Lisbon	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		U						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.33	1.94	9.09	135.67	4.71	0.81	7.95	119.55	3.38	-1.13	-1.14	-16.12	
Trim / Thin Trees	3.98	1.10	8.38	125.07	3.86	0.70	6.66	100.15	-0.12	-0.40	-1.72	-24.92	
Encroachments	0.07	0.03	0.19	2.84	0.06	0.02	0.14	2.11	-0.01	-0.01	-0.05	-0.73	
Animal Control	0.06		0.06	0.90	0.06		0.06	0.90					0.01
USACE Erosion Survey		0.01	0.04	0.60		0.01	0.04	0.60					0.00
<i>LMA Totals:</i>	5.44	3.08	17.76	265.07	8.69	1.54	14.85	223.31	3.25	-1.54	-2.91	-41.77	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0341	Total LMA Miles	9.62										
Reclamation District No. 0341 Sherman Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	1.96	3.06	14.20	146.39					-1.96	-3.06	-14.20	-146.39
Encroachments	0.15		0.15	1.55					-0.15		-0.15	-1.55
<i>LMA Totals:</i>	2.11	3.06	14.35	147.94	0.00	0.00	0.00	0.00	-2.11	-3.06	-14.35	-147.94
RD0349	Total LMA Miles	12.49										
Reclamation District No. 0349 Sutter Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	9.39	0.20	10.19	80.87	1.52		1.52	12.17	-7.87	-0.20	-8.67	-68.70
Trim / Thin Trees	0.54		0.54	4.29	0.99		0.99	7.93	0.45		0.45	3.64
Encroachments	0.22	0.04	0.38	3.02	0.15	0.02	0.23	1.84	-0.07	-0.02	-0.15	-1.17
USACE Erosion Survey	0.03	0.11	0.47	3.73	0.03	0.11	0.47	3.76				0.03
<i>LMA Totals:</i>	10.18	0.35	11.58	91.90	2.69	0.13	3.21	25.70	-7.49	-0.22	-8.37	-66.20
RD0369	Total LMA Miles	0.80										
Reclamation District No. 0369 Libby McNeill	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	0.16	0.22	1.04	130.00					-0.16	-0.22	-1.04	-130.00
Trim / Thin Trees	0.21	0.08	0.53	66.25					-0.21	-0.08	-0.53	-66.25
<i>LMA Totals:</i>	0.37	0.30	1.57	196.25	0.00	0.00	0.00	0.00	-0.37	-0.30	-1.57	-196.25
RD0501	Total LMA Miles	20.48										
Reclamation District No. 0501 Ryer Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	16.03	2.00	24.03	117.22	5.12	1.80	12.32	60.16	-10.91	-0.20	-11.71	-57.06
Trim / Thin Trees	0.78	1.13	5.30	25.85	1.31	0.32	2.59	12.65	0.53	-0.81	-2.71	-13.21
Encroachments	0.01	0.03	0.13	0.63	0.01		0.01	0.05		-0.03	-0.12	-0.59
Animal Control	3.30		3.30	16.10	3.30		3.30	16.11				0.01
Erosion / Bank Caving	0.06		0.06	0.29	0.06		0.06	0.29				0.00
Cracking	0.29	0.33	1.61	7.85	1.30	0.34	2.66	12.99	1.01	0.01	1.05	5.13
Crown Surface / Depressions / Rutting	0.18		0.18	0.88	0.18		0.18	0.88				0.00
USACE Erosion Survey	0.11	0.01	0.15	0.73	0.11	0.01	0.15	0.73				0.00
<i>LMA Totals:</i>	20.76	3.50	34.76	169.56	11.39	2.47	21.27	103.86	-9.37	-1.03	-13.49	-65.70

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0536	Total LMA Miles 10.63											
Reclamation District No. 0536 Egbert	Fall 2008				Fall 2009				Change			
	Overall LMA Rating U				Overall LMA Rating U							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	11.54	4.41	29.18	272.71	8.43		8.43	79.30	-3.11	-4.41	-20.75	-193.41
Trim / Thin Trees	0.08		0.08	0.75	0.08		0.08	0.75				0.01
Encroachments					0.01		0.01	0.09	0.01		0.01	0.09
Erosion / Bank Caving	0.01		0.01	0.09	0.01		0.01	0.09				0.00
Crown Surface / Depressions / Rutting	4.78	0.67	7.46	69.72	2.05		2.05	19.29	-2.73	-0.67	-5.41	-50.43
<i>LMA Totals:</i>	16.41	5.08	36.73	343.27	10.58	0.00	10.58	99.53	-5.83	-5.08	-26.15	-243.74
RD0537	Total LMA Miles 5.95											
Reclamation District No. 0537 Lovdal	Fall 2008				Fall 2009				Change			
	Overall LMA Rating A				Overall LMA Rating M							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.37		0.37	6.17	0.69		0.69	11.60	0.32		0.32	5.43
Trim / Thin Trees					0.02		0.02	0.34	0.02		0.02	0.34
Erosion / Bank Caving					0.01		0.01	0.17	0.01		0.01	0.17
USACE Erosion Survey	0.01		0.01	0.17	0.01		0.01	0.17				0.00
<i>LMA Totals:</i>	0.38	0.00	0.38	6.33	0.73	0.00	0.73	12.27	0.35	0.00	0.35	5.94
RD0551	Total LMA Miles 6.84											
Reclamation District No. 0551 Pierson	Fall 2008				Fall 2009				Change			
	Overall LMA Rating U				Overall LMA Rating A							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.99	0.14	1.55	22.79					-0.99	-0.14	-1.55	-22.79
Trim / Thin Trees	0.07		0.07	1.03					-0.07		-0.07	-1.03
Encroachments	0.25	0.03	0.37	5.44	0.03		0.03	0.44	-0.22	-0.03	-0.34	-5.00
Animal Control	1.17		1.17	17.21					-1.17		-1.17	-17.21
<i>LMA Totals:</i>	2.48	0.17	3.16	46.47	0.03	0.00	0.03	0.44	-2.45	-0.17	-3.13	-46.03
RD0554	Total LMA Miles 1.09											
Reclamation District No. 0554 Walnut Grove	Fall 2008				Fall 2009				Change			
	Overall LMA Rating U				Overall LMA Rating U							
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01	0.83	3.33	277.50	0.34		0.34	31.19	0.33	-0.83	-2.99	-246.31
Trim / Thin Trees	0.04	0.14	0.60	50.00					-0.04	-0.14	-0.60	-50.00
Encroachments		0.02	0.08	6.67					-0.02	-0.08	-6.67	
<i>LMA Totals:</i>	0.05	0.99	4.01	334.17	0.34	0.00	0.34	31.19	0.29	-0.99	-3.67	-302.97

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0556	Total LMA Miles 11.19											
Reclamation District No. 0556 Upper Andrus	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U	Overall LMA Rating		U						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	7.40	5.76	30.44	271.79	14.44	8.30	47.64	425.74	7.04	2.54	17.20	153.95
Trim / Thin Trees	0.48	0.89	4.04	36.07	0.05	0.25	1.05	9.38	-0.43	-0.64	-2.99	-26.69
Encroachments	0.05	0.03	0.17	1.52	0.06	0.03	0.18	1.61	0.01	0.01	0.09	
Animal Control					5.29		5.29	47.27	5.29		5.29	47.27
Slope Stability		0.29	1.16	10.36		0.29	1.16	10.37				0.01
Erosion / Bank Caving					0.01		0.01	0.09	0.01		0.01	0.09
Cracking					0.61		0.61	5.45	0.61		0.61	5.45
USACE Erosion Survey	0.37	0.20	1.17	10.45	0.37	0.14	0.93	8.31		-0.06	-0.24	-2.14
<i>LMA Totals:</i>	8.30	7.17	36.98	330.18	20.83	9.01	56.87	508.22	12.53	1.84	19.89	178.04

RD0563	Total LMA Miles 12.38											
Reclamation District No. 0563 Tyler Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U	Overall LMA Rating		U						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	18.99	0.60	21.39	172.50	0.10	1.31	5.34	43.13	-18.89	0.71	-16.05	-129.37
Trim / Thin Trees	0.60	0.32	1.88	15.16	0.17	0.08	0.49	3.96	-0.43	-0.24	-1.39	-11.20
Encroachments	1.98	0.02	2.06	16.61	1.02		1.02	8.24	-0.96	-0.02	-1.04	-8.37
Slope Stability		0.01	0.04	0.32		0.01	0.04	0.32				0.00
Erosion / Bank Caving						0.01	0.04	0.32		0.01	0.04	0.32
Crown Surface / Depressions / Rutting					0.49		0.49	3.96	0.49		0.49	3.96
USACE Erosion Survey	2.10	0.51	4.14	33.39	1.87	0.51	3.91	31.58	-0.23		-0.23	-1.80
<i>LMA Totals:</i>	23.67	1.46	29.51	237.98	3.65	1.92	11.33	91.52	-20.02	0.46	-18.18	-146.47

RD0755	Total LMA Miles 1.86											
Reclamation District No. 0755 Randall	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U	Overall LMA Rating		A						
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.36		0.36	18.95					-0.36		-0.36	-18.95
Trim / Thin Trees	0.01		0.01	0.53					-0.01		-0.01	-0.53
Encroachments	0.01	0.01	0.05	2.63					-0.01	-0.01	-0.05	-2.63
Animal Control	0.06		0.06	3.16	0.04		0.04	2.15	-0.02		-0.02	-1.01
Slope Stability	0.04		0.04	2.11					-0.04		-0.04	-2.11
Crown Surface / Depressions / Rutting	0.01		0.01	0.53					-0.01		-0.01	-0.53
<i>LMA Totals:</i>	0.49	0.01	0.53	27.89	0.04	0.00	0.04	2.15	-0.45	-0.01	-0.49	-25.74

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0765	Total LMA Miles	1.74											
Reclamation District No. 0765 Glide	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		U						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.07	0.24	1.03	60.59	0.11		0.11	6.32	0.04	-0.24	-0.92	-54.27	
Trim / Thin Trees	0.53	0.14	1.09	64.12	0.49	0.05	0.69	39.66	-0.04	-0.09	-0.40	-24.46	
Encroachments	0.01		0.01	0.59	0.01		0.01	0.58				-0.01	
<i>LMA Totals:</i>	0.61	0.38	2.13	125.29	0.61	0.05	0.81	46.55	0.00	-0.33	-1.32	-78.74	
RD0784	Total LMA Miles	38.43											
Reclamation District No. 0784 Plumas Lake	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.71		0.71	2.02	0.32		0.32	0.83	-0.39			-0.39	-1.18
Erosion / Bank Caving	0.03		0.03	0.09					-0.03			-0.03	-0.09
<i>LMA Totals:</i>	0.74	0.00	0.74	2.10	0.32	0.00	0.32	0.83	-0.42	0.00	-0.42		-1.27
RD0785	Total LMA Miles	5.61											
Reclamation District No. 0785 Driver	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		M						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.15		0.15	2.68	0.59		0.59	10.52	0.44			0.44	7.84
Encroachments					0.01		0.01	0.18	0.01			0.01	0.18
Crown Surface / Depressions / Rutting					0.05		0.05	0.89	0.05			0.05	0.89
<i>LMA Totals:</i>	0.15	0.00	0.15	2.68	0.65	0.00	0.65	11.59	0.50	0.00	0.50		8.91
RD0787	Total LMA Miles	4.40											
Reclamation District No. 0787 Fair	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.04		0.04	0.91					-0.04			-0.04	-0.91
<i>LMA Totals:</i>	0.04	0.00	0.04	0.91	0.00	0.00	0.00	0.00	-0.04	0.00	-0.04		-0.91
RD0817	Total LMA Miles	9.19											
Reclamation District No. 0817 Carlin	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.11		0.11	1.20	0.09		0.09	0.98	-0.02			-0.02	-0.22
Encroachments	0.01		0.01	0.11					-0.01			-0.01	-0.11
Crown Surface / Depressions / Rutting	0.23		0.23	2.50	0.17		0.17	1.85	-0.06			-0.06	-0.65
<i>LMA Totals:</i>	0.35	0.00	0.35	3.80	0.26	0.00	0.26	2.83	-0.09	0.00	-0.09		-0.98

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD0827	Total LMA Miles	4.19										
Reclamation District No. 0827 Elkhorn	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	0.47		0.47	11.19	0.18		0.18	4.30	-0.29		-0.29	-6.89
Trim / Thin Trees	0.13		0.13	3.10	0.13		0.13	3.10				0.01
Animal Control	0.02		0.02	0.48					-0.02		-0.02	-0.48
<i>LMA Totals:</i>	0.62	0.00	0.62	14.76	0.31	0.00	0.31	7.40	-0.31	0.00	-0.31	-7.36
RD0900	Total LMA Miles	13.57										
Reclamation District No. 0900 West Sacramento	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		M					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	4.09	0.64	6.65	48.90	0.76	0.01	0.80	5.90	-3.33	-0.63	-5.85	-43.00
Trim / Thin Trees	1.27	0.12	1.75	12.87	0.68		0.68	5.01	-0.59	-0.12	-1.07	-7.86
Encroachments	0.02		0.02	0.15	0.01		0.01	0.07	-0.01		-0.01	-0.07
Animal Control	0.29		0.29	2.13					-0.29		-0.29	-2.13
Cracking	0.02		0.02	0.15	0.01		0.01	0.07	-0.01		-0.01	-0.07
Crown Surface / Depressions / Rutting	1.64	0.18	2.36	17.35					-1.64	-0.18	-2.36	-17.35
USACE Erosion Survey		0.01	0.04	0.29		0.01	0.04	0.29				0.00
<i>LMA Totals:</i>	7.33	0.95	11.13	81.84	1.46	0.02	1.54	11.35	-5.87	-0.93	-9.59	-70.49
RD0999	Total LMA Miles	32.37										
Reclamation District No. 0999	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	1.92	0.35	3.32	10.25	0.23	0.04	0.39	1.20	-1.69	-0.31	-2.93	-9.04
Trim / Thin Trees	4.06	1.28	9.18	28.33	3.34	0.23	4.26	13.16	-0.72	-1.05	-4.92	-15.17
Encroachments	0.91		0.91	2.81	1.03		1.03	3.18	0.12		0.12	0.37
Animal Control	1.91		1.91	5.90	1.26		1.26	3.89	-0.65		-0.65	-2.00
Crown Surface / Depressions / Rutting	0.29		0.29	0.90	1.88		1.88	5.81	1.59		1.59	4.91
USACE Erosion Survey	0.02	0.34	1.38	4.26	0.02	0.34	1.38	4.26				0.00
<i>LMA Totals:</i>	9.11	1.97	16.99	52.44	7.76	0.61	10.20	31.51	-1.35	-1.36	-6.79	-20.93
RD1000	Total LMA Miles	42.48										
Reclamation District No. 1000	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	1.30		1.30	3.05					-1.30		-1.30	-3.05
USACE Erosion Survey	0.13		0.13	0.31	0.13		0.13	0.31				0.00
<i>LMA Totals:</i>	1.43	0.00	1.43	3.36	0.13	0.00	0.13	0.31	-1.30	0.00	-1.30	-3.05

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD1001	Total LMA Miles	44.03										
Reclamation District No. 1001 Nicolaus	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Rated Item	Vegetation	5.45		5.45	12.39	0.60		0.60	1.36	-4.85		-4.85 -11.02
	Trim / Thin Trees	0.11		0.11	0.25					-0.11		-0.11 -0.25
	Encroachments	0.57		0.57	1.30	0.18		0.18	0.41	-0.39		-0.39 -0.89
	Animal Control	0.02		0.02	0.05					-0.02		-0.02 -0.05
	Slope Stability	0.03		0.03	0.07	0.01		0.01	0.02	-0.02		-0.02 -0.05
	Sluice / Slide Gates	0.01		0.01	0.02					-0.01		-0.01 -0.02
	USACE Erosion Survey	0.03	0.04	0.19	0.43	0.03	0.04	0.19	0.43			0.00
	<i>LMA Totals:</i>	6.22	0.04	6.38	14.50	0.82	0.04	0.98	2.23*	-5.40	0.00	-5.40 -12.27
RD1500	Total LMA Miles	54.35										
Reclamation District No. 1500 Sutter Basin	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Rated Item	Vegetation				0.59		0.59	1.09	0.59		0.59	1.09
	Trim / Thin Trees				0.01		0.01	0.02	0.01		0.01	0.02
	Encroachments	0.03		0.03	0.06	0.12		0.12	0.22	0.09		0.09 0.17
	Animal Control	0.07		0.07	0.13	0.10		0.10	0.18	0.03		0.03 0.06
	Erosion / Bank Caving	0.05		0.05	0.09	0.03		0.03	0.06	-0.02		-0.02 -0.04
	Crown Surface / Depressions / Rutting					0.01		0.01	0.02	0.01		0.01 0.02
	USACE Erosion Survey	0.49	0.47	2.37	4.36	0.49	0.47	2.37	4.36			0.00
	<i>LMA Totals:</i>	0.64	0.47	2.52	4.63*	1.35	0.47	3.23	5.94*	0.71	0.00	0.71 1.31
RD1600	Total LMA Miles	14.73										
Reclamation District No. 1600 Mull	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Rated Item	Vegetation	0.99		0.99	6.74	0.22		0.22	1.49	-0.77		-0.77 -5.24
	Trim / Thin Trees	0.01		0.01	0.07	0.07		0.07	0.48	0.06		0.06 0.41
	Encroachments	0.08		0.08	0.54					-0.08		-0.08 -0.54
	Animal Control					0.01		0.01	0.07	0.01		0.01 0.07
	Erosion / Bank Caving	0.66		0.66	4.49	1.01		1.01	6.86	0.35		0.35 2.37
	<i>LMA Totals:</i>	1.74	0.00	1.74	11.84	1.31	0.00	1.31	8.89	-0.43	0.00	-0.43 -2.94
RD1601	Total LMA Miles	2.47										
Reclamation District No. 1601 Twitchell	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Rated Item	Erosion / Bank Caving				0.05		0.05	2.02	0.05		0.05	2.02
	<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.05	0.00	0.05	2.02	0.05	0.00	0.05 2.02

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD1660	Total LMA Miles	12.14										
Reclamation District No. 1660 Tisdale	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Encroachments	0.01		0.01	0.08	0.01		0.01	0.08				0.00
Animal Control	0.04		0.04	0.33					-0.04		-0.04	-0.33
<i>LMA Totals:</i>	0.05	0.00	0.05	0.41	0.01	0.00	0.01	0.08	-0.04	0.00	-0.04	-0.33
RD2035	Total LMA Miles	12.09										
Reclamation District No. 2035 Conaway	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
USACE Erosion Survey	0.73		0.73	6.03					-0.73		-0.73	-6.03
<i>LMA Totals:</i>	0.73	0.00	0.73	6.03	0.00	0.00	0.00	0.00	-0.73	0.00	-0.73	-6.03
RD2060	Total LMA Miles	15.67										
Reclamation District No. 2060 Hastings	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	2.55		2.55	15.94	0.18		0.18	1.15	-2.37		-2.37	-14.79
Trim / Thin Trees	0.03		0.03	0.19					-0.03		-0.03	-0.19
Erosion / Bank Caving	0.01		0.01	0.06	0.01		0.01	0.06				0.00
Repair Gates		0.02	0.08	0.50						-0.02	-0.08	-0.50
USACE Erosion Survey	0.16		0.16	1.00	0.16		0.16	1.02				0.02
<i>LMA Totals:</i>	2.75	0.02	2.83	17.69	0.35	0.00	0.35	2.23	-2.40	-0.02	-2.48	-15.45
RD2068	Total LMA Miles	8.73										
Reclamation District No. 2068 Yolano	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	0.06		0.06	0.69					-0.06		-0.06	-0.69
<i>LMA Totals:</i>	0.06	0.00	0.06	0.69	0.00	0.00	0.00	0.00	-0.06	0.00	-0.06	-0.69
RD2098	Total LMA Miles	10.96										
Reclamation District No. 2098 Cache and Haas Slough	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles
Vegetation	0.66		0.66	5.99	1.06		1.06	9.67	0.40		0.40	3.68
Erosion / Bank Caving	0.06		0.06	0.54					-0.06		-0.06	-0.54
<i>LMA Totals:</i>	0.72	0.00	0.72	6.53	1.06	0.00	1.06	9.67	0.34	0.00	0.34	3.14

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

RD2103	Total LMA Miles 9.77											
Reclamation District No. 2103 Wheatland Vicinity	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments		0.01	0.04	0.41						-0.01	-0.04	-0.41
Animal Control	0.02		0.02	0.20	0.01		0.01	0.10	-0.01		-0.01	-0.10
Crown Surface / Depressions / Rutting	0.74		0.74	7.55					-0.74		-0.74	-7.55
Repair Gates		0.01	0.04	0.41						-0.01	-0.04	-0.41
<i>LMA Totals:</i>	0.76	0.02	0.84	8.57*	0.01	0.00	0.01	0.10	-0.75	-0.02	-0.83	-8.47

RD2104	Total LMA Miles 12.20											
Reclamation District No. 2104 Peters Pocket Tract	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.78	7.01	29.82	402.97	3.78	1.08	8.10	66.39	2.00	-5.93	-21.72	-336.58
Trim / Thin Trees	0.02	0.05	0.22	2.97	0.02	0.05	0.22	1.80				-1.17
Erosion / Bank Caving	0.01		0.01	0.14	0.02		0.02	0.16	0.01		0.01	0.03
Crown Surface / Depressions / Rutting					1.24		1.24	10.16	1.24		1.24	10.16
Repair Gates		0.01	0.04	0.54						-0.01	-0.04	-0.54
<i>LMA Totals:</i>	1.81	7.07	30.09	406.62	5.06	1.13	9.58	78.52	3.25	-5.94	-20.51	-328.10

ST0001	Total LMA Miles 25.52											
Sacramento Maintenance Yard Cache Creek	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.02		0.02	0.08	0.02		0.02	0.08				0.00
Encroachments	0.11		0.11	0.43	0.28		0.28	1.10	0.17		0.17	0.67
USACE Erosion Survey		0.28	1.12	4.34		0.28	1.12	4.39				0.05
<i>LMA Totals:</i>	0.13	0.28	1.25	4.84*	0.30	0.28	1.42	5.56*	0.17	0.00	0.17	0.72

ST0002	Total LMA Miles 22.12											
Sutter Maintenance Yard East Levee Sutter Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.07		0.07	0.31	0.06		0.06	0.27	-0.01		-0.01	-0.04
<i>LMA Totals:</i>	0.07	0.00	0.07	0.31	0.06	0.00	0.06	0.27	-0.01	0.00	-0.01	-0.04

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

ST0003	Total LMA Miles	27.17										
Sutter Maintenance Yard East Levee Sacramento River	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.55		0.55	2.02	0.02		0.02	0.07	-0.53		-0.53	-1.94
Trim / Thin Trees	0.44		0.44	1.61	0.01		0.01	0.04	-0.43		-0.43	-1.58
Encroachments	0.26		0.26	0.95	0.19		0.19	0.70	-0.07		-0.07	-0.25
Animal Control	1.30		1.30	4.76	0.86		0.86	3.17	-0.44		-0.44	-1.60
Slope Stability	0.02		0.02	0.07					-0.02		-0.02	-0.07
<i>LMA Totals:</i>	2.57	0.00	2.57	9.41	1.08	0.00	1.08	3.98	-1.49	0.00	-1.49	-5.44
ST0004	Total LMA Miles	2.00										
Sacramento Maintenance Yard East Levee Yolo Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
No Items												0.00
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
ST0005	Total LMA Miles	3.22										
Sutter Maintenance Yard Hamilton Bend	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation					1.47		1.47	45.65	1.47		1.47	45.65
Crown Surface / Depressions / Rutting	1.05		1.05	87.50					-1.05		-1.05	-87.50
<i>LMA Totals:</i>	1.05	0.00	1.05	87.50	1.47	0.00	1.47	45.65	0.42	0.00	0.42	-41.85
ST0006	Total LMA Miles	0.50										
Sutter Maintenance Yard Nelson Bend	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.10		1.10	220.00	1.10		1.10	220.00				0.00
Trim / Thin Trees	0.44		0.44	88.00	0.44		0.44	88.00				0.00
<i>LMA Totals:</i>	1.54	0.00	1.54	308.00	1.54	0.00	1.54	308.00	0.00	0.00	0.00	0.00
ST0007	Total LMA Miles	16.29										
Sacramento Maintenance Yard Putah Creek	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Trim / Thin Trees	0.23		0.23	1.41	0.11		0.11	0.68	-0.12		-0.12	-0.74
Encroachments	0.05		0.05	0.31	0.01		0.01	0.06	-0.04		-0.04	-0.25
Animal Control	0.12		0.12	0.74	0.06		0.06	0.37	-0.06		-0.06	-0.37
Erosion / Bank Caving					0.02		0.02	0.12	0.02		0.02	0.12
<i>LMA Totals:</i>	0.40	0.00	0.40	2.46	0.20	0.00	0.20	1.23	-0.20	0.00	-0.20	-1.23

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Sacramento River Basin (cont.)

ST0008	Total LMA Miles	3.51										
Sacramento Maintenance Yard Sacramento Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.01		0.01	0.28					-0.01		-0.01	-0.28
<i>LMA Totals:</i>	0.01	0.00	0.01	0.28	0.00	0.00	0.00	0.00	-0.01	0.00	-0.01	-0.28
ST0009	Total LMA Miles	8.93										
Sutter Maintenance Yard Tisdale Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.01		0.01	0.11					-0.01		-0.01	-0.11
<i>LMA Totals:</i>	0.01	0.00	0.01	0.11	0.00	0.00	0.00	0.00	-0.01	0.00	-0.01	-0.11
ST0010	Total LMA Miles	9.32										
Sutter Maintenance Yard Wadsworth Canal	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Encroachments	0.01		0.01	0.11					-0.01		-0.01	-0.11
Animal Control	0.15		0.15	1.61	0.10		0.10	1.07	-0.05		-0.05	-0.54
<i>LMA Totals:</i>	0.16	0.00	0.16	1.72	0.10	0.00	0.10	1.07	-0.06	0.00	-0.06	-0.64
ST0011	Total LMA Miles	9.33										
Sacramento Maintenance Yard West Levee Yolo Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.01		0.01	0.11					-0.01		-0.01	-0.11
USACE Erosion Survey	0.15	0.03	0.27	2.89	0.15	0.03	0.27	2.89				0.01
<i>LMA Totals:</i>	0.16	0.03	0.28	2.99*	0.15	0.03	0.27	2.89*	-0.01	0.00	-0.01	-0.10
ST0012	Total LMA Miles	12.46										
Sacramento Maintenance Yard Willow Slough Bypass	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A		Overall LMA Rating		A					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.21		0.21	1.69					-0.21		-0.21	-1.69
USACE Erosion Survey	0.54		0.54	4.33	0.54		0.54	4.33				0.00
<i>LMA Totals:</i>	0.75	0.00	0.75	6.02	0.54	0.00	0.54	4.33	-0.21	0.00	-0.21	-1.69

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin

NA0010		Total LMA Miles	197.28											
Lower San Joaquin Levee District		Fall 2008				Fall 2009				Change				
		Overall LMA Rating		M	*	Overall LMA Rating		M	*					
		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Rated Item		Vegetation	9.86		9.86	5.15	0.67		0.67	0.34	-9.19		-9.19	-4.81
Trim / Thin Trees		0.03		0.03	0.02	0.04		0.04	0.02	0.01		0.01	0.00	
Encroachments			0.01	0.04	0.02	0.10		0.10	0.05	0.10	-0.01	0.06	0.03	
Animal Control		0.70		0.70	0.37	0.81		0.81	0.41	0.11		0.11	0.05	
Crown Surface / Depressions / Rutting						4.52		4.52	2.29	4.52		4.52	2.29	
Repair Gates						0.01		0.01	0.01	0.01		0.01	0.01	
Vegetation & Obstructions		0.06		0.06	0.03					-0.06		-0.06	-0.03	
Encroachments							0.01	0.04	0.02		0.01	0.04	0.02	
DWR Erosion Survey			0.06	0.24	0.13					-0.06	-0.24	-0.13		
<i>LMA Totals:</i>		10.65	0.07	10.93	5.71*	6.15	0.01	6.19	3.14*	-4.50	-0.06	-4.74	-2.57	
NA0011	Total LMA Miles	26.65												
Madera County FCWCA				Fall 2008				Fall 2009				Change		
		Overall LMA Rating		U		Overall LMA Rating		U						
		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Rated Item		Vegetation	26.16	2.33	35.48	132.88	0.58		0.58	2.18	-25.58	-2.33	-34.90	-130.71
Trim / Thin Trees		0.18	0.05	0.38	1.42	0.17		0.17	0.64	-0.01	-0.05	-0.21	-0.79	
Encroachments		0.21	0.94	3.97	14.87	0.17	0.05	0.37	1.39	-0.04	-0.89	-3.60	-13.48	
Animal Control		7.69	1.34	13.05	48.88	8.01	0.30	9.21	34.56	0.32	-1.04	-3.84	-14.32	
Erosion / Bank Caving		0.02	0.04	0.18	0.67					-0.02	-0.04	-0.18	-0.67	
Crown Surface / Depressions / Rutting			0.01	0.04	0.15					-0.01	-0.04	-0.15		
DWR Erosion Survey		0.10		0.10	0.38	0.12		0.12	0.45	0.02		0.02	0.08	
<i>LMA Totals:</i>		34.36	4.71	53.20	199.25	9.05	0.35	10.45	39.21	-25.31	-4.36	-42.75	-160.04	
NA0013	Total LMA Miles	6.40												
Merced County Stream Group				Fall 2008				Fall 2009				Change		
		Overall LMA Rating		U		Overall LMA Rating		U						
		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Rated Item		Animal Control	1.10	2.33	10.42	165.40	2.88	1.40	8.48	132.50	1.78	-0.93	-1.94	-32.90
Crown Surface / Depressions / Rutting		0.10		0.10	1.59					-0.10		-0.10	-1.59	
DWR Erosion Survey		0.02	0.01	0.06	0.95	0.14	0.02	0.22	3.44	0.12	0.01	0.16	2.49	
<i>LMA Totals:</i>		1.22	2.34	10.58	167.94	3.02	1.42	8.70	135.94	1.80	-0.92	-1.88	-32.00	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

NA0017		Total LMA Miles		103.96									
San Joaquin County Flood Control and Water Conservation District		Fall 2008				Fall 2009				Change			
		Overall LMA Rating		M *		Overall LMA Rating		M					
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.52		2.52	2.41		3.69	0.35	5.09	4.90	1.17	0.35	2.57	2.49
Trim / Thin Trees	0.60		0.60	0.57		0.58		0.58	0.56	-0.02		-0.02	-0.02
Encroachments	1.59	0.25	2.59	2.48		3.10	0.55	5.30	5.10	1.51	0.30	2.71	2.62
Animal Control	0.29		0.29	0.28		0.33	0.01	0.37	0.36	0.04	0.01	0.08	0.08
Slope Stability	0.03		0.03	0.03		1.35		1.35	1.30	1.32		1.32	1.27
Erosion / Bank Caving	0.05		0.05	0.05		0.22		0.22	0.21	0.17		0.17	0.16
Crown Surface / Depressions / Rutting	0.81		0.81	0.78		0.11		0.11	0.11	-0.70		-0.70	-0.67
Vegetation & Obstructions						0.05	0.04	0.21	0.20	0.05	0.04	0.21	0.20
Flap Gates		0.01	0.04	0.04		0.02	0.02	0.10	0.10	0.02	0.01	0.06	0.06
Sluice / Slide Gates							0.01	0.04	0.04		0.01	0.04	0.04
Monolith Joints						0.01		0.01	0.01	0.01		0.01	0.01
DWR Erosion Survey	0.06	0.81	3.30	3.16		0.16	0.99	4.12	3.96	0.10	0.18	0.82	0.81
<i>LMA Totals:</i>	5.95	1.07	10.23	9.79*		9.62	1.97	17.50	16.83	3.67	0.90	7.27	7.04

RD0001		Total LMA Miles		1.15									
Reclamation District No. 0001 Union Island		Fall 2008				Fall 2009				Change			
		Overall LMA Rating		A		Overall LMA Rating		M					
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation						0.12		0.12	10.44	0.12		0.12	10.44
DWR Erosion Survey	0.01		0.01	0.83						-0.01		-0.01	-0.83
<i>LMA Totals:</i>	0.01	0.00	0.01	0.83		0.12	0.00	0.12	10.44	0.11	0.00	0.11	9.60

RD0017		Total LMA Miles		16.24									
Reclamation District No. 0017 Mossdale		Fall 2008				Fall 2009				Change			
		Overall LMA Rating		U		Overall LMA Rating		M *					
Rated Item		M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.45	0.02	0.53	3.27		0.03		0.03	0.19	-0.42	-0.02	-0.50	-3.09
Trim / Thin Trees	0.54	0.25	1.54	9.51						-0.54	-0.25	-1.54	-9.51
Encroachments	0.10		0.10	0.62		0.01		0.01	0.06	-0.09		-0.09	-0.56
Animal Control	1.86	0.04	2.02	12.47		1.37		1.37	8.44	-0.49	-0.04	-0.65	-4.03
Slope Stability	0.01		0.01	0.06						-0.01		-0.01	-0.06
Repair Gates	0.02		0.02	0.12						-0.02		-0.02	-0.12
DWR Erosion Survey						0.04	0.04	0.20	1.23	0.04	0.04	0.20	1.23
<i>LMA Totals:</i>	2.98	0.31	4.22	26.05		1.45	0.04	1.61	9.91*	-1.53	-0.27	-2.61	-16.14

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD0404	Total LMA Miles	4.12										
Reclamation District No. 0404 Boggs	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.33		0.33	8.05	0.01		0.01	0.24	-0.32		-0.32	-7.81
Encroachments	0.03		0.03	0.73					-0.03		-0.03	-0.73
Animal Control	0.40		0.40	9.76	0.40		0.40	9.71				-0.05
Slope Stability	0.05		0.05	1.22	0.05		0.05	1.21				-0.01
Erosion / Bank Caving	0.03		0.03	0.73	0.03		0.03	0.73				0.00
Crown Surface / Depressions / Rutting	0.38		0.38	9.27					-0.38		-0.38	-9.27
Flap Gates	0.01		0.01	0.24					-0.01		-0.01	-0.24
DWR Erosion Survey	0.09	0.29	1.25	30.49		0.30	1.20	29.13	-0.09	0.01	-0.05	-1.36
<i>LMA Totals:</i>	1.32	0.29	2.48	60.49	0.49	0.30	1.69	41.02	-0.83	0.01	-0.79	-19.47
RD0524	Total LMA Miles	6.26										
Reclamation District No. 0524 Middle Roberts Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.07	0.08	0.39	6.19	0.12	0.08	0.44	7.03	0.05		0.05	0.84
Trim / Thin Trees	0.58		0.58	9.21	0.55	0.09	0.91	14.54	-0.03	0.09	0.33	5.33
Encroachments	0.44	0.01	0.48	7.62	0.45	0.01	0.49	7.83	0.01		0.01	0.21
Animal Control	0.63		0.63	10.00	0.39		0.39	6.23	-0.24		-0.24	-3.77
Slope Stability	0.16		0.16	2.54	0.16		0.16	2.56				0.02
Erosion / Bank Caving	0.25	0.01	0.29	4.60	0.28	0.01	0.32	5.11	0.03		0.03	0.51
Crown Surface / Depressions / Rutting	0.02	0.05	0.22	3.49	0.03	0.04	0.19	3.04	0.01	-0.01	-0.03	-0.46
Erosion Areas					0.01		0.01	0.16	0.01		0.01	0.16
DWR Erosion Survey	0.02		0.02	0.32		0.24	0.96	15.34	-0.02	0.24	0.94	15.02
<i>LMA Totals:</i>	2.17	0.15	2.77	43.97	1.99	0.47	3.87	61.82	-0.18	0.32	1.10	17.85
RD0544	Total LMA Miles	10.33										
Reclamation District No. 0544 Upper Roberts Island	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		M					
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	7.10	0.45	8.90	86.41	0.12		0.12	1.16	-6.98	-0.45	-8.78	-85.25
Trim / Thin Trees	0.83		0.83	8.06	0.67		0.67	6.49	-0.16		-0.16	-1.57
Encroachments	0.52		0.52	5.05	0.25		0.25	2.42	-0.27		-0.27	-2.63
Animal Control	0.36		0.36	3.50	0.30		0.30	2.90	-0.06		-0.06	-0.59
Slope Stability	0.05		0.05	0.49	0.01		0.01	0.10	-0.04		-0.04	-0.39
Erosion / Bank Caving	0.01		0.01	0.10	0.01		0.01	0.10				0.00
Crown Surface / Depressions / Rutting	0.06		0.06	0.58		0.06	0.24	2.32	-0.06	0.06	0.18	1.74
DWR Erosion Survey		0.04	0.16	1.55		0.04	0.16	1.55				0.00
<i>LMA Totals:</i>	8.93	0.49	10.89	105.73	1.36	0.10	1.76	17.04	-7.57	-0.39	-9.13	-88.69

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD1602	Total LMA Miles	6.29										
Reclamation District No. 1602 Del Puerto	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.89		3.89	61.75	1.06		1.06	16.85	-2.83		-2.83	-44.89
Trim / Thin Trees	0.15		0.15	2.38	0.20		0.20	3.18	0.05		0.05	0.80
Encroachments	0.04		0.04	0.64	0.12		0.12	1.91	0.08		0.08	1.27
Animal Control	1.47		1.47	23.33	2.81		2.81	44.67	1.34		1.34	21.34
Slope Stability	0.01		0.01	0.16	0.04		0.04	0.64	0.03		0.03	0.48
Erosion / Bank Caving					0.01		0.01	0.16	0.01		0.01	0.16
Crown Surface / Depressions / Rutting	0.47		0.47	7.46	0.47		0.47	7.47				0.01
Encroachments	0.01		0.01	0.16	0.01		0.01	0.16				0.00
Flap Gates					0.01		0.01	0.16	0.01		0.01	0.16
Concrete Tilting / Settlement					0.01		0.01	0.16	0.01		0.01	0.16
LMA Totals:	6.04	0.00	6.04	95.87	4.74	0.00	4.74	75.36	-1.30	0.00	-1.30	-20.52
RD2031	Total LMA Miles	13.19										
Reclamation District No. 2031 Elliot	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M *		Overall LMA Rating		M *					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.11		0.11	0.83	0.10	0.04	0.26	1.97	-0.01	0.04	0.15	1.14
Trim / Thin Trees	0.22		0.22	1.67	0.60		0.60	4.55	0.38		0.38	2.88
Encroachments	0.01		0.01	0.08	0.30		0.30	2.27	0.29		0.29	2.20
Animal Control					0.05		0.05	0.38	0.05		0.05	0.38
Crown Surface / Depressions / Rutting		0.09	0.36	2.73	0.02		0.02	0.15	0.02	-0.09	-0.34	-2.58
DWR Erosion Survey		0.10	0.40	3.03	0.04		0.04	0.30	0.04	-0.10	-0.36	-2.73
LMA Totals:	0.34	0.19	1.10	8.33*	1.11	0.04	1.27	9.63*	0.77	-0.15	0.17	1.30
RD2058	Total LMA Miles	6.71										
Reclamation District No. 2058 Pescadero	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.58	0.05	0.78	11.64	1.17	0.04	1.33	19.82	0.59	-0.01	0.55	8.18
Trim / Thin Trees	0.18	0.21	1.02	15.22	0.35	0.18	1.07	15.95	0.17	-0.03	0.05	0.72
Encroachments	0.03		0.03	0.45	0.24		0.24	3.58	0.21		0.21	3.13
Animal Control					0.12	0.01	0.16	2.38	0.12	0.01	0.16	2.38
Slope Stability	0.01		0.01	0.15					-0.01		-0.01	-0.15
DWR Erosion Survey		0.04	0.16	2.39	0.05		0.05	0.75	0.05	-0.04	-0.11	-1.64
LMA Totals:	0.80	0.30	2.00	29.85	1.93	0.23	2.85	42.47	1.13	-0.07	0.85	12.62

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD2062	Total LMA Miles	12.35										
Reclamation District No. 2062 Stewart	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M	*	Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.02		0.02	0.16	0.01		0.01	0.08	-0.01		-0.01	-0.08
Encroachments					1.40		1.40	11.34	1.40		1.40	11.34
Animal Control					0.07		0.07	0.57	0.07		0.07	0.57
Slope Stability					0.01		0.01	0.08	0.01		0.01	0.08
Crown Surface / Depressions / Rutting					2.55		2.55	20.65	2.55		2.55	20.65
DWR Erosion Survey	0.06	0.12	0.54	4.39	0.16	0.11	0.60	4.86	0.10	-0.01	0.06	0.47
<i>LMA Totals:</i>	0.08	0.12	0.56	4.55*	4.20	0.11	4.64	37.57	4.12	-0.01	4.08	33.02
RD2063	Total LMA Miles	10.63										
Reclamation District No. 2063 Crows Landing	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		U					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	6.59		6.59	62.17	2.66	0.01	2.70	25.40	-3.93	0.01	-3.89	-36.77
Trim / Thin Trees	0.03		0.03	0.28	0.04		0.04	0.38	0.01		0.01	0.09
Encroachments	0.02	0.01	0.06	0.57		0.01	0.04	0.38	-0.02		-0.02	-0.19
Animal Control					0.04	0.07	0.32	3.01	0.04	0.07	0.32	3.01
Slope Stability	0.01		0.01	0.09					-0.01		-0.01	-0.09
Crown Surface / Depressions / Rutting	0.34		0.34	3.21	0.24		0.24	2.26	-0.10		-0.10	-0.95
Flap Gates	0.02		0.02	0.19	0.01		0.01	0.09	-0.01		-0.01	-0.10
Sluice / Slide Gates		0.01	0.04	0.38	0.01		0.01	0.09	0.01	-0.01	-0.03	-0.28
DWR Erosion Survey	0.01		0.01	0.09	0.01		0.01	0.09				0.00
<i>LMA Totals:</i>	7.02	0.02	7.10	66.98	3.01	0.09	3.37	31.70	-4.01	0.07	-3.73	-35.28
RD2064	Total LMA Miles	11.90										
Reclamation District No. 2064 River Junction	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		M		Overall LMA Rating		A					
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	1.30		1.30	10.92					-1.30		-1.30	-10.92
Erosion / Bank Caving	0.01		0.01	0.08	0.01		0.01	0.08				0.00
<i>LMA Totals:</i>	1.31	0.00	1.31	11.01	0.01	0.00	0.01	0.08	-1.30	0.00	-1.30	-10.92
RD2075	Total LMA Miles	7.52										
Reclamation District No. 2075 McMullin	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U		Overall LMA Rating		M	*				
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	3.71		3.71	49.47					-3.71		-3.71	-49.47
Trim / Thin Trees	0.05		0.05	0.67					-0.05		-0.05	-0.67
Encroachments	0.38	0.01	0.42	5.60	0.01		0.01	0.13	-0.37	-0.01	-0.41	-5.47
DWR Erosion Survey		0.03	0.12	1.60		0.01	0.04	0.53		-0.02	-0.08	-1.07
<i>LMA Totals:</i>	4.14	0.04	4.30	57.33	0.01	0.01	0.05	0.66*	-4.13	-0.03	-4.25	-56.67

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD2085	Total LMA Miles	6.18										
Reclamation District No. 2085 Kasson	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U	Overall LMA Rating		M						
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.79		0.79	12.74					-0.79		-0.79	-12.74
Trim / Thin Trees	1.47		1.47	23.71	0.20		0.20	3.24	-1.27		-1.27	-20.47
Encroachments	0.02		0.02	0.32	0.48		0.48	7.77	0.46		0.46	7.44
Animal Control					0.04	0.10	0.44	7.12	0.04	0.10	0.44	7.12
Slope Stability					0.02		0.02	0.32	0.02		0.02	0.32
Erosion / Bank Caving	0.01		0.01	0.16					-0.01		-0.01	-0.16
Crown Surface / Depressions / Rutting	0.05		0.05	0.81					-0.05		-0.05	-0.81
Underseepage Relief Wells		0.02	0.08	1.29						-0.02	-0.08	-1.29
Metal Pipes					0.01		0.01	0.16	0.01		0.01	0.16
<i>LMA Totals:</i>	2.34	0.02	2.42	39.03	0.75	0.10	1.15	18.61	-1.59	0.08	-1.27	-20.42
RD2089	Total LMA Miles	2.90										
Reclamation District No. 2089 Stark	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		U	Overall LMA Rating		U						
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.26	2.08	8.58	295.86	0.82	0.29	1.98	68.28	0.56	-1.79	-6.60	-227.59
Trim / Thin Trees	0.85	0.12	1.33	45.86	0.21	0.19	0.97	33.45	-0.64	0.07	-0.36	-12.41
Encroachments					0.01		0.01	0.35	0.01		0.01	0.35
Animal Control	0.03	0.01	0.07	2.41	0.07		0.07	2.41	0.04	-0.01		0.00
Crown Surface / Depressions / Rutting	0.76		0.76	26.21					-0.76		-0.76	-26.21
DWR Erosion Survey	0.04	0.03	0.16	5.52	0.03	0.03	0.15	5.17	-0.01		-0.01	-0.34
<i>LMA Totals:</i>	1.94	2.24	10.90	375.86	1.14	0.51	3.18	109.66	-0.80	-1.73	-7.72	-266.21
RD2091	Total LMA Miles	7.92										
Reclamation District No. 2091 Chase	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A	Overall LMA Rating		A						
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.62		0.62	7.83					-0.62		-0.62	-7.83
Trim / Thin Trees	0.16		0.16	2.02					-0.16		-0.16	-2.02
<i>LMA Totals:</i>	0.78	0.00	0.78	9.85	0.00	0.00	0.00	0.00	-0.78	0.00	-0.78	-9.85
RD2092	Total LMA Miles	3.76										
Reclamation District No. 2092 Dos Rios	Fall 2008				Fall 2009				Change			
	Overall LMA Rating		A	Overall LMA Rating		A						
	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.07		0.07	1.84					-0.07		-0.07	-1.84
Encroachments	0.01		0.01	0.26					-0.01		-0.01	-0.26
Animal Control					0.04		0.04	1.06	0.04		0.04	1.06
Slope Stability	0.01		0.01	0.26					-0.01		-0.01	-0.26
Flap Gates					0.01		0.01	0.27	0.01		0.01	0.27
DWR Erosion Survey	0.14		0.14	3.68	0.14		0.14	3.72				0.04
<i>LMA Totals:</i>	0.23	0.00	0.23	6.05	0.19	0.00	0.19	5.05	-0.04	0.00	-0.04	-1.00

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD2094	Total LMA Miles	3.28											
Reclamation District No. 2094 Wathal	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		A						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Animal Control	0.19		0.19	5.76						-0.19		-0.19	-5.76
Erosion / Bank Caving	0.01		0.01	0.30	0.01		0.01	0.31					0.00
Crown Surface / Depressions / Rutting					0.01		0.01	0.31	0.01		0.01		0.31
<i>LMA Totals:</i>	0.20	0.00	0.20	6.06	0.02	0.00	0.02	0.61	-0.18	0.00	-0.18		-5.45
RD2095	Total LMA Miles	4.83											
Reclamation District No. 2095 Paradise Cut	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		M						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	1.82		1.82	37.14	0.04	0.01	0.08	1.66	-1.78	0.01	-1.74		-35.49
Trim / Thin Trees	0.72		0.72	14.69					-0.72		-0.72		-14.69
Encroachments	0.02		0.02	0.41	0.01		0.01	0.21	-0.01		-0.01		-0.20
Erosion / Bank Caving	0.81		0.81	16.53	0.01		0.01	0.21	-0.80		-0.80		-16.32
DWR Erosion Survey	0.01	0.06	0.25	5.10		0.10	0.40	8.28	-0.01	0.04	0.15		3.18
<i>LMA Totals:</i>	3.38	0.06	3.62	73.88	0.06	0.11	0.50	10.35	-3.32	0.05	-3.12		-63.53
RD2096	Total LMA Miles	0.17											
Reclamation District No. 2096 Wetherbee Lake	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A		Overall LMA Rating		U						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	0.01		0.01	5.00	0.01		0.01	5.88					0.88
Animal Control	0.01		0.01	5.00	0.06		0.06	35.29	0.05		0.05		30.29
<i>LMA Totals:</i>	0.02	0.00	0.02	10.00	0.07	0.00	0.07	41.18	0.05	0.00	0.05		31.18
RD2101	Total LMA Miles	3.51											
Reclamation District No. 2101 Blewett	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U		Overall LMA Rating		U						
	Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %
Vegetation	2.75		2.75	78.57	2.88		2.88	82.05	0.13		0.13		3.48
Trim / Thin Trees	1.88		1.88	53.71	1.88		1.88	53.56					-0.15
Encroachments					0.01		0.01	0.29	0.01		0.01		0.29
Animal Control	0.14		0.14	4.00	0.03		0.03	0.86	-0.11		-0.11		-3.15
Erosion / Bank Caving		0.02	0.08	2.29	0.01		0.01	0.29	0.01	-0.02	-0.07		-2.00
Crown Surface / Depressions / Rutting	0.20		0.20	5.71	0.02		0.02	0.57	-0.18		-0.18		-5.14
DWR Erosion Survey		0.10	0.40	11.43		0.10	0.40	11.40					-0.03
<i>LMA Totals:</i>	4.97	0.12	5.45	155.71	4.83	0.10	5.23	149.00	-0.14	-0.02	-0.22		-6.71

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

San Joaquin River Basin (cont.)

RD2107	Total LMA Miles	4.21											
Reclamation District No. 2107	Fall 2008				Fall 2009				Change				
	Overall LMA Rating	A	Overall LMA Rating	A									
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	0.22		0.22	5.24					-0.22		-0.22	-5.24	
Trim / Thin Trees	0.05		0.05	1.19					-0.05		-0.05	-1.19	
Encroachments	0.01		0.01	0.24	0.06		0.06	1.43	0.05		0.05	1.19	
Slope Stability					0.01		0.01	0.24	0.01		0.01	0.24	
<i>LMA Totals:</i>	0.28	0.00	0.28	6.67	0.07	0.00	0.07	1.66	-0.21	0.00	-0.21	-5.00	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report

Overall LMA Ratings, Compare 2008 & 2009

Miscellaneous Streams & Basins

MA0017	Total LMA Miles	3.90											
Sutter Maintenance Yard Maintenance Area 0017	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		U	Overall LMA Rating		U							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation		3.13	12.52	321.03		3.13	12.52	321.03				0.00	
Trim / Thin Trees		3.12	12.48	320.00		3.12	12.48	320.00				0.00	
<i>LMA Totals:</i>	0.00	6.25	25.00	641.03	0.00	6.25	25.00	641.03	0.00	0.00	0.00	0.00	

NA0009	Total LMA Miles	10.47											
Lake County Watershed Protection District	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A	Overall LMA Rating		A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
Vegetation	0.23		0.23	2.07	0.01		0.01	0.10	-0.22		-0.22	-1.98	
Trim / Thin Trees	0.19		0.19	1.71	0.02		0.02	0.19	-0.17		-0.17	-1.52	
Encroachments	0.04		0.04	0.36	0.01		0.01	0.10	-0.03		-0.03	-0.26	
Erosion / Bank Caving	0.10		0.10	0.90					-0.10		-0.10	-0.90	
<i>LMA Totals:</i>	0.56	0.00	0.56	5.05	0.04	0.00	0.04	0.38	-0.52	0.00	-0.52	-4.66	

NA0015	Total LMA Miles	3.22											
Plumas County	Fall 2008				Fall 2009				Change				
	Overall LMA Rating		A	Overall LMA Rating		A							
Rated Item	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	M Miles	U Miles	M+4U Miles	Thresh. %	
No Items												0.00	
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	

* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.